

NOTES


Sidewalk Deficiencies

Location	Description	Affected Area
1.	Uneven sidewalk	3' x 3'
2.	Uneven sidewalk	4' x 24'
3.	Uneven sidewalk	4' x 88'
4.	Uneven sidewalk	4' x 20'
5.	Uneven sidewalk	4' x 100'
6.	Uneven sidewalk	4' x 4'
7.	Overgrown shrubbery	6' x 12'
8.	Overgrown sidewalk	6' x 10'
9.	Uneven sidewalk	3' x 10'
10.	Uneven sidewalk	6' x 3'
11.	Cracked sidewalk	6' x 150'

No Sidewalks

- **M. Place**
Location 12. Length 740'
- **M. Street**
Location 13. Length 300'
- **Anacostia Road**
Location 14. Length 300'
15. Length 300'
16. Length 260'
17. Length 1020'
- **N Street**
Location 18. Length 1020'
19. Length 650'
20. Length 325'
- **31st Street**
Location 21. Length 250'
22. Length 250'
- **Nash Place**
Location 23. Length 350'
24. Length 150'
- **D Street**
Location 25. Length 1120'
- **P Street**
Location 26. Length 1120'
27. Length 1060'
- **Q Street**
Location 28. Length 350'
29. Length 500'
- **30th Street**
Location 30. Length 230'
31. Length 240'
32. Length 50'
33. Length 250'
34. Length 280'
35. Length 280'
36. Length 270'
- **Branch Street**
Location 37. Length 100'
38. Length 330'
39. Length 95'
40. Length 250'
41. Length 350'
42. Length 550'
43. Length 140'
44. Length 270'

LOCATION



TITLE

**30TH ST. – BRANCH AVE
DEFICIENCIES**

LEGEND/NOTES

- LEGEND**
- ND SIDEWALK
 - SIDEWALK
 - BUFFER

PROJECT
PENN BRANCH AVENUE
TRAFFIC-CALMING STUDY

PREPARED FOR:

PREPARED BY:



DATE: JUNE 2007

FIGURE

PAGE# 7

6